

Santa Ynez Community Service District Vulnerability Study of Sewer Creek Crossing

Field priority 1	Field priority 2 or 3	Field priority 4	Field priority 5
Exposed and / or damaged sewer line	Erosion is evident	No immediate threat (low vulnerability)	No vulnerability evident
Immediate threat	High vulnerability to sewer or force main	Does not require further evaluation	Does not require further evaluation or monitoring
Immediate action necessary	Requires further evaluation	Long-term effects of erosion should be monitored	No action required

Reach	Reach	Reach	Reach

Creek Crossing ID No.	Reaches	Depth to invert - ft	Location	Field Priority	Spill Risk Factor	Wt. Rank
1	33 to 34	4.83	Alamo Pintado Creek	4	1	4
2	119 to C/O 119A	2	East side of park S. C. C.	4	2	8
3	124 to 229	2	Tyndall St north of Sagunto in creek	3	2	6
4	229 to 232	4	Tyndall St north of Sagunto in creek	4	3	12
5	229 to 125	4	Tyndall St north of Sagunto in creek	4	2	8
6	188 to 189	8.42	Catarina off track	5	4	20
7	188 to 187	7.42	Catarina off track	5	5	25
8	188 to 190	5.33	Catarina off track	5	5	25
9	190 to 191	4.5	Catarina off track	4	5	20
10	186 to 187	0	Catarina off track at Pine St	1	2	2
11	213 to 228	5	Tivola west sideCreek	5	5	25
12	75 to 76	3.92	Long horn off trackCreek	4	4	16
13	113 to 114	4	Old Calzada off track Creek	4	3	12
14	113 to C/O 113A	0	Old Calzada off track CreekCreek	1	2	2
15	113 TO 112	0	Old Calzada off track Creek	2	3	6
16	145 to 146	4.5	Pine street off track	4	4	16
17	144 to 143	10.08	Pine street off track	5	5	25
18	143 to C/O 143A	6.92	Pine street off track	5	5	25

19	72 to 73		Long horn off trackCreek	unkown	3	#VALUE!
20	143 to 142	12	Pine street off track	5	5	25
21	Force main	3.5	246	2	1	2